


Safetyscope



*No one knows
confined spaces*



Fall arrest inertia
reel complete with
rescue winch

Safetyscope

2501 Rutherford Road Unit 22
Vaughan, Ontario L4K 2N6

Phone: 416.231.3752
Fax: 416.231.2811

E-mail: training@safetyscope.net



SAFETYScope

Davit Arm / Tripod / Fall Arrest Tower Inspection

The Ministry of Labour's incident investigations found that some welds to be deficient and that they may fail to support the structural loads applied to the system during hoisting. It is recommended that where davit systems are installed the employer should conduct inspections prior to work commencing. If the welds or other component of the system are defective, the system should be withdrawn from service the appropriate corrective action is taken.

Type A Inspection \$200.00

This inspection will be a full operation evaluation of the unit and upon successful completion, Safetyscope will issue an inspection certificate for one year. The inspection will include:

- Visual inspection of each system component in accordance to manufactures instructions..
- Inspect all welds for metal fatigue, cracks, dents and distortion
- Inspect pins and their fitting to ensure all lock properly
- Ensure pins , and their fittings are present and lock properly
- pins , and their fitting
- Inspect entire system for corrosion
- Inspect stickers visibility (replace as needed.)

Type B inspection

This require a quote for all parts and labour for repairs of deficient parts above plus cost of Type A inspection.

Safetyscope will issue an inspection certificate for one year.